

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4850	DATE	Nov.12.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the resin fuel tank of the subject vehicles, due to improper welding control in the welding process, there is a possibility that the weld seam of the fuel tank could be welded insufficiently. In this condition, the weld seam could separate by fluctuation of the inner pressure of the tank, which could result in a fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-DB22	[SUPRA]	2019-2020	9
3BA-DB42		2019	3
3BA-DB82			1
		TOTAL	13