

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3127	DATE	November 12th , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the resin fuel tank of the subject vehicles, due to improper welding control in the welding process, there is a possibility that the weld seam of the fuel tank could be welded insufficiently. In this condition, the weld seam could separate by fluctuation of the inner pressure of the tank, which could result in a fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-HF20	「BMW Z4 sDrive 20i」	2019	3
3BA-HF30	「BMW Z4 M40i」	2019	1
		TOTAL	4