

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	gai-3125	DATE	November 25 , 2020
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Concerning the engine blow-by gas reduction device, due to inappropriate maintenance control of manufacturing equipment for the intake manifolds, some blow-by gas intake ports may have been blocked. Because of that, unburned gas does not flow into the intake manifold, and the internal pressure of the crankcase increases, which will cause engine malfunction and turning on the warning light for oil level. At the worst case, the engine will break.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KWH5F1	KANGOO 1.2 L - EDC	2019	25
		TOTAL	25