

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-3128	Date	2020/11/25
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	A HUB of pump couling may have been assembled incorrectly, then it can bring insufficient coupling engagement and cause breakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-H22	「910M」	<b>2019-2020</b>	18
		TOTAL	18