

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4853	DATE	November 26, 2020
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	The steering joint, connecting the intermediate shaft and the steering gear box of the steering system, may not have been installed in its normal position due to inadequate assembling work instructions. Such steering joint can, if the vehicle continues in service, come off the steering gear box, whereby the vehicle could be rendered unsteerable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-JH3	「N-WGN」	2019-2020	387
6BA-JH4	「N-WGN Custom」		58
		TOTAL	445