

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4852	DATE	Dec.2.2020
MANUFACTURER	TOYOTA TMT		
DESCRIPTION OF DEFECT	In the brake booster of the subject vehicles, due to an improper molding condition of the resin piston, there is a possibility that the piston may have decreased strength. If this were to occur, the piston may break by repeated operation of the brake pedal, and in the worst case, braking assist may be lost while driving, increasing the vehicle stopping distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDF-GUN125	[HILUX]	2018-2019	4,087
		TOTAL	4,087