VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3136	DATE	December 2nd, 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The drainage design of the right side of cowl cover panel which locate above the reservoir tank of the brake master cylinder is inappropriate rainwater may enter the brake fluid. It became gel and clog in the hydraulic control unit, which can cause the brakes to continue operate even when the brake pedal is released.		ylinder is inappropriate, me gel and clog in the brakes to continue to

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-1A16	BMW 116i		11.327
	BMW 118i	2013 - 2015	55
	BMW 120i		668
DBA-1B30	BMW M135i	2013 - 2015	790
DBA-1J30	BMW M235i	2013 - 2015	842
DBA-1J20	BMW 220i	2014 - 2015	717
		TOTAL	14,399