## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4851	DATE	Dec. 3. 2020	
MANUFACTURER	NISSAN			
DESCRIPTION OF DEFECT	Regarding the propeller shaft, due to inadequate material adoption and inappropriate dimensions, it may be cracked. Therefore, if the driver continues to drive in this condition, in the worst case, the propeller shaft may be broken by progressing the crack and it may be unable to drive.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HY51	NISSAN FUGA	$2 0 1 0 \sim 2 0 1 4$	8,388
DAA-HGY51	NISSAN CIMA	$2 0 1 2 \sim 2 0 1 9$	4,319
DAA-BHGY51	MITSUBISHI DIGNITY	$2 0 1 2 \sim 2 0 1 6$	121
		TOTAL	12,828