VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4859	DATE	December 4, 2020		
MANUFACTURER	Komatsu Ltd.				
DESCRIPTION OF DEFECT	As for the dumper coupling which is mounted on the connection part between the forklift engine and the hydraulic pump of the forklift, the tightening of the mounting bolt was not appropriately done. Therefore, there is a risk that the damper coupling can slip out of the hydraulic pump. This can make the hydraulic pump unable to drive and the forklift unable to run properly.				

TYPE	COMMERCIAL NAME	,	MODEL YEAR CALLED	NUMBER OF VEHICLE
YDR-M289	「FH100-1」 「FH120-1」 「FH135-1」	20	18-2020	25
	「FH160-1」		TOTAL	25