

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3134	DATE	December 8, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	The rubber seal is cured by heat from the turbocharger due to insufficient of heat resistance. As a result, the seal is cracked and the debris is come loose, and in the worst case, the vehicle fire is broken out when the loosed debris come into contact with hot area in the engine compartment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4HCEUF	Audi A8 4.0Tq	2013	213
ABA-4HCEUL	Audi A8L 4.0Tq	2013	70
ABA-4HCGTF	Audi S8	2013	224
ABA-4HCTFF	Audi S8	2014-2016	229
ABA-4HCTGF	Audi A8 4.0Tq	2014-2017	733
ABA-4HCTGL	Audi A8L 4.0Tq	2014-2017	115
ABA-4HDDTF	Audi S8 plus	2016-2017	146
		Total	1,730