

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3135	DATE	December 8, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	In exhaust system, an incorrect catalytic converter may have been installed because of improper production control in the catalytic converter assembly process. The catalytic converter may be deteriorated early, and engine warning lamp in the instrument cluster may be come on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FVCJXF	Audi TTS	2020	42
		Total	42