

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4857	DATE	December 10, 2020
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	<p>(1)The software of the power control module has a programing error, which may cause to improperly control fuel injection when large amount of fuel vapor enter the combustion chamber. As a result, the amount of fuel injection may be insufficient to maintain proper engine combustion. Engine may ultimately stall during low speed driving.</p> <p>(2)The software of the power control module has a programing error in automatic engine start/stop system operation, which may cause engine not to restart properly if the engine condition determination process is delayed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-BP5P	Mazda「MAZDA3」	2019	1 0
5BA-BPFP		2019	1 2
		Total	2 2