

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4860	DATE	December 10 ,2020
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>In this defect relating to the light-duty trucks shown below, each equipped with a freezer unit as its rear body, the structure of where the idle pully for the belt driving the freezer unit's compressor is fitted on the cylinder block with a fastening bolt is inappropriate, so that in some of the said trucks, the fastening bolt receives excessive stress due to belt tension and thus breaks down, possibly causing the belt to come off and resulting in the freezer unit malfunctioning and, in the worst case, the pully falling on the road while the trucks are running.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-NHR88AN	[ELF]	2019-2020	153
2RG-NHS88AN		2019-2020	28
2RG-NJR88AN		2019-2020	194
2RG-NJS88AN		2019-2020	34
2RG-NKR88AN 2RG-NKR88N		2019-2020	4
2PG-NKS88AN 2RG-NKS88AN		2019-2020	12
2RG-NLR88AN 2RG-NLR88N 2SG-NLR88AN		2018-2020	1,227
2RG-NLS88AN		2019-2020	132
2RG-NMR88AN 2RG-NMR88N 2SG-NMR88AN		2018-2020	594
2PG-NMS88AN 2RG-NMS88AN		2019-2020	47
2PG-NPR88AN 2PG-NPR88N 2RG-NPR88AN 2RG-NPR88N 2SG-NPR88AN		2018-2020	2,319

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2PG-NPR88YN 2RG-NPR88YN	[ELF]	2018-2020	222
2PG-NPS88AN 2RG-NPS88AN		2019-2020	120
2RG-AHR88AN	[ATLAS]	2019-2020	47
		TOTAL	5,133

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2RG-NMR88AN 2RG-NMR88N	[ELF]	2019-2020	2
		TOTAL	2

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Idle Pulley Bracket	8-98344194-3	2019-2020	5
		TOTAL	5