

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4862	DATE	December 17, 2020
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the fuel devices of internal-combustion engine forklift and shovel loader vehicles, there are cases where strength of injector body is insufficient due to improper manufacturing process. There is a possibility that repeated common rail pressure may cause cracks at the inlet of the injector, and lead to fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-A8FDL18	TOYOTA GENE0	2018 - 2019	112
YDN-A8FDL25		2018 - 2019	205
YDN-A8FDL30		2018 - 2019	3
YDN-A8FD18		2018 - 2019	26
YDN-A8FD25		2018 - 2019	194
YDN-A8FDJ35		2018 - 2019	184
YDN-A6SD7	TOYOTA SHOVEL LOADER	2018	1
YDN-A6SD12		2019	1
		TOTAL	726