

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4867	DATE	December 17, 2020
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Fuel tanks may have been manufactured under inadequate control over foreign matters whereby oxides may have been generated in such fuel tanks during the course of welding. Such oxides can get caught in the fuel pump suction filter and eventually clog the filter. Should this happen, the engine could go wrong and, in the very worst case, stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-SD10	「CRF1100L Africa Twin」	2019-2020	1,177
2BL-SD04	「CRF1000L Africa Twin」	2018-2019	878
		TOTAL	2,055