

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4650	DATE	Jan.30,2020
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>In the driver side frontal airbag inflator of the subject vehicles, the propellant could absorb the moisture due to insufficient protection against moisture absorption into the propellant.</p> <p>Due to the above, there is a possibility that the airbag does not inflate properly in the event of the airbag deployment, after the repeated moisture absorption and drying of the propellant.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
GF-TA02W	ESCUDO	1997~1999	1,438
GF-TA52W			98
GF-TD02W			1,838
KD-TD32W		1998	89
GF-TD52W		1997~1999	2,907
GF-TD62W		1998~1999	839
GF-TL52W			1,186
GF-TF52W	PROCEED LEVANTE	1997~1999	144
KD-TJ32W		1998~1999	119

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
GF-TJ52W	PROCEED LEVANTE	1997～1999	1,311
GF-TJ62W		1998～1999	303
		TOTAL	10,272