

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4870	DATE	January 6, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper manufacturing control, the breather hose between fuel vapor emission control devices (canister) and the fuel tank is not connected. As a result, fuel vapor may leak into the atmosphere, making it impossible to comply with the Article 31 of the safety standards (Device for preventing emission of harmful gas).</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-ED13N	GIXXER	2020	866
2BK-ED22B		2020	1,444
		TOTAL	2,310