VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai – 3154	DATE	13, Jan, 2020
MANUFACTURER	Hyundai Motor Company (Japanese importer : Hyundai Motor Japan Co., Ltd)		
DESCRIPTION OF DEFECT	In the software of the IEB module, there is a defect in the fail-safe logic, so if the motor motion detection sensor malfunctions and an abnormal signal occurs, the warning light will light up, and in the worst case, the braking assistance will be limited, and Braking distance may increase.		tions and an abnormal I in the worst case, the

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZBA-FE120	NEXO	2020. Apr. ~ 2020. Apr	6
UNKNOWN		2019. Feb. ~ 2019. Feb.	5
		TOTAL	11