

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3155	DATE	January 14, 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Brake boosters which potentially have a faulty hydraulic valve were installed in the vehicles due to inappropriate setting of the manufacturing tool of the hydraulic valve. In this case, correct brake fluid flow may not be assured, resulting in brake malfunction warning light which will not comply with Japanese safety regulation Article 15.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-CV30A	「BMW X5 xDrive 35d」	2020	5
3BA-JU44A	「BMW X5 M50i」	2020	1
3BA-JU44M	「BMW X5M」	2020	3
	「BMW X6M」	2020	4
3DA-GT30	「BMW X6 xDrive 35d」	2020	2
3BA-CY44	「BMW X6 M50i」	2020	1
3DA-CW30	「BMW X7 xDrive35d」	2020	12
TOTAL			28