

## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4873	DATE	Jan. 21, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the improper work instruction, the front seat belt may be partly stuck behind the interior trim of the center pillar at the time of the assembly, and it may have the excessive slack.</p> <p>The above situation may result in the delay of restraining of the occupant and the degree of injury may be increased, as the slacked part of the seat belt is being pulled out at the time of the collision.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
4AA-MR52S	HUSTLER	2019~2020	19,684	
5AA-MR92S			42,489	
DBA-MH35S	WAGON R	2017	376	
DAA-MH55S			3,647	
4AA-MS52S	FLAIR CROSSOVER	2020	1,078	
5AA-MS92S			3,506	
<b>TOTAL</b>			<b>70,780</b>	