

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4879	DATE	January 21, 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Driver's airbag inflator is inadequately prevented from absorbing moisture whereby gas generating propellant contained therein may absorb moisture. Should gas generating propellant be moisturized and dried repeatedly while the vehicle continues in service, the inflator could fail to properly inflate the airbag in the event of airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E-RH1	「S-MX」	1998-1999	2,896
E-RH2			436
		TOTAL	3,332