

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3159	DATE	January 21, 2021
MANUFACTURER	HONDA OF AMERICA MFG., INC.		
DESCRIPTION OF DEFECT	Driver's airbag inflator is inadequately prevented from absorbing moisture whereby gas generating propellant contained therein may absorb moisture. Should gas generating propellant be moisturized and dried repeatedly while the vehicle continues in service, the inflator could fail to properly inflate the airbag in the event of airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E-EJ7	「CIVIC COUPE」	1995-1996	171
		TOTAL	171