

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4871	DATE	January 22. 2021
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In the engine harness of agricultural tractor, the harness and the engine mount bracket interfere with each other due to improper arrangement instructions. Therefore, if you continue to use it as it is, the corrugated tube that protects the electric wire in the harness will open due to vibration etc., the coating of the electric wire will come into contact with the engine mount bracket, and in the worst case, the wiring will be damaged. There is a risk of stopping engine or the headlights not turning on.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「YT463」	2015~2016	343	
	「YT470」	2015~2016	348	
		TOTAL	691	