

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4875	DATE	January 22. 2021
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	Some agricultural tractor clutches are not manufactured correctly due to improper processing of bearing sleeves. Therefore, stress concentration occurs in the bearing sleeve during the clutch operation, and a part of the sleeve is damaged, so that the clutch cannot be operated, and there is a possibility that the speed cannot be changed or the tractor cannot run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「GK13」	2020	60	
	「GK14」	2020	61	
-	「GK16」	2020	73	
		2020	58	
	「GK18」	2008	1	Assembled as spare part
-	「Ke-18」	2010	1	Assembled as spare part
TOTAL			254	