

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4878	DATE	Jan. 28. 2021
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In a drive-train, hydraulic pressure may leak due to abnormal wear of the valve body. When hydraulic pressure leaks, due to the improper program of the AT control computer, it may not detect failure properly which results in insufficient detection of hydraulic pressure leakage. If a vehicle with this condition is used over time, in the worst case, as continuous usage leads to increase in hydraulic pressure leakage, an unintentional clutch engage occurs, which may cause sudden deceleration of vehicle speed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S500P	HIJET TRUCK	2014-2020	73,925
3BD-S500P			
EBD-S510P		2014-2020	136,297
3BD-S510P			
EBD-S321V	HIJET	2015-2020	203,898
HBD-S321V			
3BD-S321V			
5BD-S321V			
EBD-S331V	HIJET DECKVAN	2015-2020	94,604
HBD-S331V			
3BD-S331V		2015-2020	4,815
5BD-S331V			
EBD-S321W	HIJET DECKVAN	2015-2020	4,815
3BD-S321W			
EBD-S331W		2015-2020	6,182
3BD-S331W			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-S321G	ATRAI WAGON	2015-2020	16,383
3BA-S321G			
ABA-S331G		2015-2020	10,400
3BA-S331G			
EBD-S500J	SAMBAR TRUCK	2014-2020	3,741
3BD-S500J			
EBD-S510J		2014-2020	9,668
3BD-S510J			
EBD-S321B	SAMBAR	2015-2020	11,544
HBD-S321B			
3BD-S321B			
5BD-S321B			
EBD-S331B		2015-2020	7,805
HBD-S331B			
3BD-S331B			
5BD-S331B			
EBD-S321Q	SAMBAR OPENDECK	2015-2020	100
3BD-S321Q			
EBD-S331Q		2015-2020	208
3BD-S331Q			
ABA-S321N	DIAS	2015-2020	1,178
ABA-S331N		2015-2020	1,493
EBD-S500U	PIXIS TRUCK	2014-2020	4,331
3BD-S500U			
EBD-S510U		2014-2020	7,498
3BD-S510U			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S321M	PIXIS VAN	2015-2020	19,909
HBD-S321M			
3BD-S321M			
5BD-S321M			
EBD-S331M		2015-2020	10,126
HBD-S331M			
3BD-S331M			
5BD-S331M			
		TOTAL	624,105