VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4881	DATE	Jan. 28. 2021	
MANUFACTURER	Hino Motors, Ltd.			
DESCRIPTION OF DEFECT	On certain bus door anti-trap detectors (photoelectric devices), they may detect that there is an obstacle even though there is no obstacle because			
	of incomplete examination of external factors such as water droplets adhering to the phototube and ambient light. Therefore, the anti-trap system may be activated, causing the automatic door for getting on and off not to be opened and closed.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-KV290N3	[HINO BlueRibbon]	2019~2020	103
2KG-KV290N3			
2TG-KV290N3			
2PG-KV290Q3		2019~2020	114
2RG-KV290Q3			
2TG-KV290Q3			
2KG-KR290J4	[HINO Rainbow]	2019~2020	214
2SG-HL2ANBP	[HINO BlueRibbon	2020	15
2SG-HL2ASBP	Hybrid]	2020	1
		TOTAL	447