

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	4883	DATE	January 29 ,2021
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		On certain heavy-duty tractors with relocated fuel tanks, the support brackets fixing the brackets of the fuel tank may have been improperly welded, causing crack formation thereat. If this were to occur, these cracks could grow over time, in the worst case, lead the fuel tank to get inclined and separated while driving.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
QPG-EXR77BG	"GIGA"	January 10,2017~April 10,2018	11
2PG-EXR77CG		June 14,2019~August 20,2020	11
		TOTAL	22