

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4901	DATE	2. Mar. 2021
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to an inappropriate control program of the on-board diagnostics in the Engine Control Unit (ECU), failure of the atmospheric pressure sensor may not be detected. Therefore, there is a possibility that the control program of the on-board diagnostics in the ECU does not comply with Article 31 (Standards for On-Board Diagnostics) of the Safety Standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-RN65J	YZF-R1	2020~2021	313
	YZF-R1M	2020	70
		TOTAL	383