

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3187	DATE	March 3 rd , 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to a failure in the tempering process at sub supplier's production, one or both output drive shafts at the rear were not hardened properly according to specification and may not fulfil the durability requirements. Thus, the output shaft can break by vehicle driving vibration, which can lead to a loss of power transmission in the drivetrain or the parking lock not functioning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-JS30	「BMW 540i xDrive」	2020	2
		TOTAL	2