

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4904	DATE	Mar. 4 2021
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some light-duty trucks, the production process of the side guards was improper and the number of spot welds connecting the corner side guards and the side guard bars is insufficient. If the vehicle continues to be used in this condition, the corner side guards may fall off from the side guard bars.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FEAV0	「FUSO CANTER」	2020~2020	2
2PG-FEB50		2020~2020	2
2PG-FEB90		2020~2020	2
		TOTAL	6