

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 9 0 2	DATE	Mar. 4. 2021
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the driver's airbag sold as repair parts, due to improper welding at the supplier, so the bracket may come off the steering wheel. Therefore, in worst case, the air bag may not deploy correctly and the occupant protection performance might be decreased.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-PU31	N I S S A N P R E S A G E	2 0 0 6	4
DBA-TU31		- 2 0 0 7	
CBA-J31	N I S S A N T I A N A	2 0 0 7	3
CBA-TNJ31			
		TOTAL	7