

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 9 0 0	DATE	Mar. 4. 2021
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the driver's airbag, due to inappropriate manufacturing condition, the airbag may not be folded properly, so heat shields to protect the fabric from the hot gas of the inflator are improperly placed. Therefore, the air bag fabric may tear and the occupant protection performance might be decreased.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-ME0	e - N V 2 0 0	2 0 1 9 ~ 2 0 2 0	14
		TOTAL	14