

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4897	DATE	March 4, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper selection of a bulb specification in a headlight, resonance occurs on the bulb at a specific engine speed and the filament may vibrate largely up and down. Therefore, if continued to be used under this condition, the filament may be broken and the headlight may become unlit.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-DN11A	GSX250R	2017-2018	3,548
		TOTAL	3,548