

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-3180	DATE	4/March/2021
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	In Volvo Cars assembly plant it's possible to twist, torsion or bend (due to human error) the cable harness during assembly, causing either the brake fluid level sensor cable (split from harness) to touch the exhaust manifold heatshield.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[XC40]	2021	2,112
		TOTAL	2,112