

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4905	DATE	Mar.5, 2021
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the electric brake booster, since the assembly position of the rotation angle sensor, which is an internal component, to the motor shaft of the magnet is inappropriate, the software may misrecognize the stroke value of the brake pedal when the ignition is turned on. Therefore, the battery may go up, resulting in the cruise control to not be set and the brake lamp to continue to light, or the warning light may turn on causing the brake pedal stepping force to be heavy.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4BA-VN5	「LEVORG」	2020 ~ 2021	12,094
		TOTAL	12,094