## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3189	DATE	March 8 <sup>th</sup> , 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The hydraulic unit in the integrated brake system has not been produced according to specifications. The rotor of the motor was not welded correctly to the shaft, which may cause rotor to slip through on the shaft.		
	As a result, the motor may not be functioning correctly, which could result in a loss of braking force support and consequently in an extended braking distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-7R30	BMW 740i	2020	6
3DA-7S30	BMW 740d xDrive	2020	3
3LA-7D30	BMW 745e	2020	4
3BA-7R44	BMW 750i xDrive	2020	1
3BA-GV30	BMW 840i GranCoupe	2020	13
3BA-AE30	BMW 840i Coupe	2020	3
3DA-GW30	BMW 840dx GranCoupe	2020	4
3DA-CV30A	BMW X5 xDrive 35d	2020	3
3LA-TA30	BMW X5 xDrive 45e	2020	1
3DA-GT30	BMW X6 xDrive 35d	2020	3
3DA-CW30	BMW X7 xDrive 35d	2020	1
7BA-AE44M	BMW M8 Coupe	2020	1
3BA-GV44	BMW M850i GranCoupe	2020	3
		TOTAL	46