

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4907	DATE	Mar.9 2021
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some large-sized route buses, the maximum combustion pressure may exceed the allowable limit for connecting rods because the engine ECU control program is inappropriate. If the vehicle is continuously used in this condition, cracks may occur in the connecting rods. In the worst case, the connecting rods will break, the vehicle will become unable to drive, and a fire will occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-MP35FM	「FUSO AERO STAR」	2013~2014	16
QDG-MP35FP		2013~2014	22
QKG-MP35FK		2013~2017	46
QKG-MP35FM		2013~2017	330
QKG-MP35FP		2013~2017	261
QKG-MP37FK		2013~2014	217
QKG-MP37FM		2013~2014	89
QKG-MP38FK		2014~2017	838
QKG-MP38FM		2014~2017	327
		TOTAL	2,146