

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4910	DATE	March 17, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to the optical axis of the headlight is adjusted under incorrect condition in the production on some vehicles, the direction of the optical axis may not comply with the safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-ED13N	GIXXER	2020	1
		2020	1
		2020	1
2BK-ED22B		2020	1
2BJ-CE47A	ADDRESS 110	2020	1
		TOTAL	5