

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4917	DATE	March 25, 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Impeller (plastic impeller) for low pressure fuel pump may swell and deform in fuel as may have become low in plastic density under improper molding conditions. In this case, the impeller can interfere with the pump cover whereby the fuel pump can be precluded from functioning properly and, in the very worst case, such malfunctioning of the fuel pump could cause the engine to stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-RW1	「CR-V」	2019	2,558
DBA-RW2			1,359
6AA-RT5			3,528
6AA-RT6			3,096
6AA-ZE4	「INSIGHT」	2019-2020	7,139
DBA-FC1	「CIVIC」	2019	1,640
DAA-KC2	「LEGEND」	2019	110
		TOTAL	19,430