

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3197	DATE	March 25, 2021
MANUFACTURER	HONDA OF THE UK MANUFACTURING LTD.		
DESCRIPTION OF DEFECT	Impeller (plastic impeller) for low pressure fuel pump may swell and deform in fuel as may have become low in plastic density under improper molding conditions. In this case, the impeller can interfere with the pump cover whereby the fuel pump can be precluded from functioning properly and, in the very worst case, such malfunctioning of the fuel pump could cause the engine to stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-FK7	「CIVIC」	2019-2020	4,376
6BA-FK7			2,159
DBA-FK8			390
		TOTAL	6,925