

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4918	DATE	Mar.26 2021
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some heavy-duty trucks with a mechanical automatic transmission, an ignition OFF signal may be incorrectly transmitted because the ignition switch is improper. As a result, problems such as the engine suddenly stopping or the headlights turning off when the light switch is used in the auto position may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FP74GGR	「FUSO SUPER GREAT」	2020~2021	7
2RG-FP74HDR		2020~2021	564
2RG-FP74HER		2020~2021	294
2RG-FP74HGR		2020~2020	44
2PG-FS70HZ		2020~2021	76
2PG-FS74GY		2020~2020	5
2PG-FS74GZ		2020~2021	40
2PG-FS74HY		2020~2021	40
2PG-FS74HZ		2019~2021	1,948
2PG-FS75GY		2020~2020	3
2PG-FS75GZ		2020~2020	11
2PG-FS75HZ		2020~2021	304
2PG-FU70GY		2020~2020	34
2PG-FU70HY		2020~2021	36
2PG-FU74GY		2020~2021	24
2PG-FU74GZ		2020~2021	60
2PG-FU74HY		2020~2021	41
2PG-FU74HZ		2020~2021	734
2PG-FU75GZ		2020	1
2PG-FU75HZ		2020~2021	193
2KG-FV70GX		2020~2021	64
2PG-FV70GX		2020~2020	42
2PG-FV70GY		2020~2021	17
2PG-FV70GZ		2020~2020	7
2KG-FV70HJR		2020~2021	113
2PG-FV70HX		2020~2021	310
2PG-FV70HY		2020~2021	99
2PG-FV70HZ		2020~2021	91
2PG-FV74GZ		2020~2021	19
2PG-FV74HJR		2020~2020	16

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV74HJR	「FUSO SUPER GREAT」	2020~2020	7
2PG-FV74HZ		2020~2021	152
2PG-FY70GY		2020~2020	3
2PG-FY70HY		2020~2021	27
2PG-FY74GY		2020~2021	14
2PG-FY74HY		2020~2021	66
		TOTAL	5,506