

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4912	DATE	Mar.26,2021
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	On some Aerial Work Platforms, etc., the rear reflector mounting position are incorrect and therefore do not comply with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
BDG-XZU354E	HINO 「HINO DUTRO」	2011	2
SKG-XZU600F		2011 - 2012	8
TKG-XZU600F		2012 - 2017	34
TKG-XZU602F		2018 - 2019	2
2KG-XZU600F		2018 - 2020	21
BDG-FC6JGWA	HINO 「HINO RANJER」	2011	2
SKG-FC9JGAP		2011 - 2012	42
TKG-FC9JGAP		2012 - 2018	377
2KG-FC2ABA		2018 - 2021	86
PDG-NKR85YN	ISUZU 「ISUZU ELF」	2011	1
SKG-NKR85YN		2011 - 2015	41

TKG-NKR85YN	ISUZU 「ISUZU ELF」	2015 - 2017	37
TPG-NKR85N		2018 - 2019	2
2PG-NKR88YN		2019 - 2021	18
SKG-NPR85YN		2012 - 2015	25
TKG-NPR85YN		2016 - 2017	11
2PG-NPR88YN		2020 - 2021	47
PKG-FRR90S1		ISUZU 「FORWARD」	2011
SKG-FRR90S1	2012 - 2013		44
TKG-FRR90S1	2013 - 2018		168
2RG-FRR90S1	2018 - 2021		181
TKG-XZU600W	TOYOTA 「TOYOTA DYNA」	2012 - 2020	6
2KG-XZU600W		2018 - 2020	7
		TOTAL	1165