

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3200	DATE	March. 30. 2021
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In vehicles that are equipped with the option 05AE multifunctional turn indicator bulb, the center taillight may fail occurred when operate the brake while ringing the horn. The brake light is thereby no longer operational. The driver will receive a Check Control message in the TFT display. A terminal change will temporarily rectify the fault.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-R12MA	「BMW R1250GS」	2021	88
2BL-R12MA	「BMW R1250GSA」	2021	164
		TOTAL	252

* R1250GSA stands for R1250GS Adventure.