

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	4925	DATE	March 31, 2021	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to the lighting device for Heavy-duty trucks, due to improper crimping of wiring terminals for headlight switch, some of the contact resistance at the terminals may become increase. Thus, the terminals might have conduction failure, upon which the headlight may have a risk of becoming disable.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD5CA	Quon	2017	6	
2PG-CD5CL	Quon	2017	1	
2PG-CG5CA	Quon	2017 - 2018	4	
2PG-CW5AL	Quon	2017 - 2018	4	
2PG-CW5BL	Quon	2017	1	
2PG-CW5CL	Quon	2017	2	
2PG-GK5AAD	Quon	2017	1	
		TOTAL	19	