

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) / Import Vehicles

CAMPAIGN No.	4911	DATE	March 31, 2021
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>Tire roller has the following issues.</p> <p>After refueling, if the tank cap is not installed properly, water may enter through the refueling port. Therefore, before performing the drainage maintenance of the water separator, the water storage capacity is exceeded, water infiltrates into the engine, the fuel device is rusted, and spraying is defective. In the worst case, the engine stops and might not be able to restart.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
WDP-TAB	ZC220P-5	2014-2017	369	
WDP-N22A2	HN220WHH-3	2014-2017	48	
YDN-TAC	ZC220P-6	2017-2021	384	
YDN-N22A5	HN220WHH-5	2017-2021	28	
		TOTAL	829	