

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4952	DATE	May 13,2021
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper crimping of the connector terminal connecting the inner wiring inside the column switch, insulator may generate at the gap between the terminal and the wiring, resulting in poor continuity.</p> <p>As a result, the headlamps, the width indicator lamps, the front fog lamps, the tail lamps, the license plate lamps, and the interior light which operates with the column switch may not illuminate or may blink, or the turn signal lamps may not illuminate.</p>		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2012~2019	58,295
DBA-CV2W		2011~2019	12,936
DBA-CV4W		2009~2011	8,324
DBA-CV5W		2009~2019	29,914
		TOTAL	129,469