

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4953	DATE	14-May-21
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	The return spring of the accelerator pedal of an agricultural tractor may be damaged due to improper manufacturing process. If the spring is damaged, the vehicle speed will not decrease even if operator takes foot off the accelerator pedal. Note that the vehicle can be stopped by operating the clutch pedal or the brake pedal.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-MRB	MR800 MR800-PC	2019~2021	122
	MR900 MR900-PC	2019~2020	72
	GV800 GVK800	2019~2020	6
	GV900	2019~2020	6
YDR-MRA	MR1000 MR1000-PC MR1000A MR1000A-PC	2019~2020	414
	GV1000 GVK1000	2019~2021	33
YDP-MRD	MR800H MR800H-PC	2019~2021	42
	MR900H MR900H-PC	2019~2020	20
	GV800H GVK800H	2020	3
	GV900H	2021	1
YDR-MRC	MR1000H MR1000H-PC	2019~2021	90
	MR1050H MR1050H-PC	2019~2021	170
	GV1000H	2020	1
	GV1050H GVK1050H	2020	7
		TOTAL	987

[Notes]

The range of vehicle numbers for recalled vehicles may include vehicles that are not.