

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4950	DATE	May 14, 2021
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	<p>In some power transmission devices, the tightening torque of the component (main transmission rod) that connects the main transmission lever and the driving HST (Hydro-Static Transmission) is insufficient. Therefore, if the use is continued as it is, the connecting component of the main transmission may come off and the vehicle may not be able to drive.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「YDN-C435」	「WR460N」	2020	122
		TOTAL	122