

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4947	DATE	May. 14, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The fuel feeding impeller in the fuel pump, which is made of the resin material, may be swollen and deformed in fuel due to the insufficient material density caused by the improper injection molding process. The impeller may interfere with the fuel pump housing, resulting in the fuel pump malfunction. In the worst case, it could cause the engine stalling while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
DAA-MN71S	XBEE	2018	16,934	
3BA-JB64W			12,280	
3BA-JB74W			2,685	
DBA-MK32S (revision)	SPACIA	2017	159	The Vehicle with a boarding slope device for wheelchairs
DAA-MK42S (revision)			86	
DAA-MK53S (revision)		2018~2019	1,776	
DBA-MM32S (revision)	FLAIR WAGON	2017	60	
DAA-MM53S (revision)		2018~2019	220	
		TOTAL	34,200	