

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4946	DATE	May. 14, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the improper design of the driver side and the passenger side door harnesses , the lead wires in the harness could be damaged /cut by the repeated motion of opening / closing the doors.</p> <p>As the result, the functions such as the curtain air bag, the side air bag and the door mirror turn signal light may become inoperative.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
3BA-JB64W	JIMNY	2018~2020	80,932	
3BA-JB74W			30,679	
		TOTAL	111,611	